

LOCTITE®

8065 Anti-seize Sticks



Product Description

LOCTITE® LB 8065™ provides the following product characteristics:

Technology	Anti-Seize
Chemical type	Naphthenic oil
Appearance	Copper color ^{LMS}
Appearance (form)	Stick
Cure	Non-curing
Application	Lubrication

LOCTITE® LB 8065™ provides a shield against high temperature seizing and galling. All mated parts, studs, bolts, flanges and gaskets, remove more easily and in cleaner and better condition. This product can be used on copper, brass, cast iron, steel, all alloys including stainless steel, all plastics and all non-metallic gasketing materials. Typical applications include original equipment and maintenance, and equipment associated with petroleum chemicals, steel mills, power plants, marine and foundries. This product is typically used in applications up to 982°C.

Typical Properties of Uncured Material

Specific gravity @ 25°C	1.18
Flash point – see SDS	
Penetration, ISO 2137, 1/10mm	20 to 80 ^{LMS}
Copper Corrosion, ISO 2160	Slight tarnish, 1a
Dimensional Stability @ 77°C	Pass

Typical Performance

An anti-seize lubricant used on a bolt helps to develop greater clamp load for the same torque compared to an unlubricated bolt. An additional benefit is greater uniformity in clamp load among a series of bolts. The relationship between torque and clamp load is expressed in the following equation:

$$T = K \times F \times D$$

T = Torque (N·m, lb.in, lb.ft)

K = Torque coefficient or nut factor, determine experimentally

F = Clamp load (N, lb.)

D = Nominal diameter of bolt (mm, in.)

Torque coefficient, k:	
SAE grade 5, class 2, phosphate coated steel nuts and bolts	0.16
SAE grade 5, class 2, phosphate coated steel nuts and bolts, solvent cleaned, not lubricated	0.19

General Information

This product is not recommended for use in pure oxygen and/or oxygen rich systems and should not be selected as a sealant for chlorine or other strong oxidizing materials.

For safe handling information on this product, consult the Safety Data Sheet (SDS).

Directions for Use:

- 1 For best performance the mating surface should be clean and free of grease.
- 2 **Note: when grinding or wire brushing, use a dust mask.** Dust from cleaning threads may contain metal compounds. Inhalation may cause lung injury or other harm.
- 3 Apply thin coating to threads and flats of nuts and bolts, assemble.

Loctite Material Specification

LMS dated November-13, 2002. Test reports for each batch are available for the indicated properties. LMS test reports include selected QC test parameters considered appropriate to specifications for customer use. Additionally, comprehensive controls are in place to assure product quality and consistency. Special customer specification requirements may be coordinated through Henkel Quality.

Storage

Store product in the unopened container in a dry location. Storage information may be indicated on the product container labelling.

Optimal Storage: 8°C to 21°C. Storage below 8°C or greater than 28°C can adversely affect product properties.

Material removed from containers may be contaminated during use. Do not return product to the original container. Henkel Corporation cannot assume responsibility for product which has been contaminated or stored under conditions other than those previously indicated. If additional information is required, please contact your local Technical Service Center or Customer Service Representative.

Conversions

(°C x 1.8) + 32 = °F	N/mm ² x 145 = psi
kV/mm x 25.4 = V/mil	MPa x 145 = psi
mm / 25.4 = inches	N·m x 8.851 = lb·in
µm / 25.4 = mil	N·m x 0.738 = lb·ft
N x 0.225 = lb	N·mm x 0.142 = oz·in
N/mm x 5.71 = lb/in	mPa·s = cP