


# Air Preparation

## Micro Gauge



Part No	Pressure	Measurements	Temp.
K-PR010B-P1	0-10 Bar	27mm X 16.8mm	-20°C- to 70°C